

*This is to certify that:*

**BMI Group – Watson Road Resource Recovery**

*ABN: 91 010 843 606/ Address: 146 Watson Road, Acacia Ridge QLD 4110*

*has successfully undergone the Waste Audit  
in accordance with the Green Star Construction & Demolition Waste Reporting Criteria for  
**Waste Processing Facilities***

**Valid through:** **22/Jul/2024**  
Review Period: 01/07/2022 – 01/07/2023

*Auditor signature:* Hannah Lewis  
*Issued on:* 21/07/2023

Issuing organisation:  
**Viridis Australasia Pty Ltd**



Contributing to Healthy and Sustainable Built Environment since 2005

*Auditor:*  
**Hannah Lewis**  
*h.Lewis@viridis.com.au*



*Lead Environmental Management Systems Auditor Exemplar Global  
Certificate #C-424584  
Scopes: Environmental Management Audit / ISO14001:2015 Audit /  
Regulatory Compliance / Waste Auditing*

*Overall audit findings:*

Criterion 1:	Full Compliance
Criterion 2:	Full Compliance
Criterion 3:	Full Compliance

**Audit result:** **Full Compliance**