

This is to certify that:

BMI Group – Nudgee Road Resource Recovery

ABN: 75 134 052 645/ Address: 538 Nudgee Road, Hendra QLD 4011

*has successfully undergone the Waste Audit
in accordance with the Green Star Construction & Demolition Waste Reporting Criteria for
Waste Processing Facilities*

Valid through: **22/Jul/2027**
Review Period: 01/07/2025 – 01/07/2026

Auditor signature: 
Issued on: 21/07/2026

Issuing organisation:

Viridis Australasia Pty Ltd



Green Building
Council Australia

viridis | Building
Environment
Consultants

Contributing to Healthy and Sustainable Built Environment since
2005

Auditor:

Hannah McAulay

h.mcaulay@viridis.com.au



**Exemplar
Global**

Lead Environmental Management Systems Auditor Exemplar

Global Certificate #C-424584

Scopes: Environmental Management Audit / ISO14001:2015

Audit / Regulatory Compliance / Waste Auditing

Overall audit findings:

Criterion 1: Full Compliance

Criterion 2: Full Compliance

Criterion 3: Full Compliance

Audit result: Full Compliance