

This is to certify that:

BMI Group – Stapylton Resource Recovery

ABN: 82 611 003 724/ Address: 144 Rossmanns Road, Stapylton QLD 4207

*has successfully undergone the Waste Audit
in accordance with the Green Star Construction & Demolition Waste Reporting Criteria for
Waste Processing Facilities*

Valid through: **22/Jul/2027**
Review Period: **01/07/2025 – 01/07/2026**

Auditor signature: 
Issued on: **21/07/2026**

Issuing organisation:

Viridis Australasia Pty Ltd  **Green Building Council Australia**

viridis | **Building Environment Consultants**

Contributing to Healthy and Sustainable Built Environment since 2005

Auditor:

Hannah McAulay

h.mcaulay@viridis.com.au



Exemplar Global

Lead Environmental Management Systems Auditor Exemplar

Global Certificate #C-424584

Scopes: Environmental Management Audit / ISO14001:2015

Audit / Regulatory Compliance / Waste Auditing

Overall audit findings:

Criterion 1: Full Compliance

Criterion 2: Full Compliance

Criterion 3: Full Compliance

Audit result: **Full Compliance**